


Glynde and Beddingham Parish Council

Inspection Report

This report shows Findings and Tasks recorded during the Inspection(s) matching the selection criteria set in the Report Wizard. If no Findings or Tasks are shown, none were recorded.

Each Inspection includes a declaration signed by the Inspector stating that no defects were found other than those recorded.

Inspections included in this report

Provider	Lewes District Council	 28/10/2024
Site Name	Glynde Play Area	
Actual Date	28/10/2024 08:07:13	
Inspection Type	Playground-Routine Visual	
Inspector	Nicky Soltermann	
Inspection Status	Completed	

Finding Summary


Glynde Play Area Findings

Asset	Finding Title	Creation Date	Resolve By Date	Risk Level
- Clatter Bridge	Item - Timber rotting	30/05/2023 08:35:41		Medium
Easy Access Roundabout	Carousel - Bearings - Worn	30/05/2023 08:43:44		Medium
- Surface	Surface - Edges Shrunk	29/06/2023 10:44:00		Medium
Rota web climber - Surface	Surface - Trip points	29/06/2023 10:58:20		Medium
2 bay swing Unit	Item - Cracked	30/08/2023 13:31:01		Medium
Wood Palisade fencing	Fencing - Panel damaged	26/06/2024 12:09:38		Medium
- Towers and platforms	Delamination of Wood	29/07/2024 12:58:51		Medium
Wood Palisade fencing	Item - Broken	29/07/2024 13:03:53		Medium
Wooden fence gate	Item - Repair/s - Minor	31/01/2022 11:06:35		Low
- Clatter Bridge	Item - Timber rotting	30/01/2023 12:07:28		Low
2 bay swing Unit	Item - Broken	30/01/2023 12:21:26		Low
- Towers and platforms	Item - Timber rotting	27/09/2023 11:19:57		Low
Football Goal	Item - Missing	28/10/2024 08:15:19		Low
Free standing Slide	Item - Missing	28/10/2024 08:16:50		Low
Spring platform	Delamination of Wood	28/10/2024 08:19:37		Low

Inspection - Glynde Play Area - 28/10/2024 08:07:13

Provider	Lewes District Council
Site Name	Glynde Play Area
Actual Date	28/10/2024 08:07:13
Inspection Type	Playground-Routine Visual
Inspector	Nicky Soltermann
Inspection Status	Completed

28/10/2024



Site Name	Glynde Play Area
Address	
Postcode	
Notes	

Findings reported within the Inspection

Football Goal - Finding

Asset	Football Goal
Finding Title	Item - Missing
Finding Group	Maintenance
Cause	
Finding Status	Open
Finding Creation Date	28/10/2024 08:15:19
Resolve By Date	
Finding Resolved Date	
Risk Level	Low
Finding Notes	Goal is missing

Finding Photos



Free standing Slide - Finding

Asset	Free standing Slide
Finding Title	Item - Missing
Finding Group	Maintenance
Cause	
Finding Status	Open
Finding Creation Date	28/10/2024 08:16:50
Resolve By Date	
Finding Resolved Date	
Risk Level	Low
Finding Notes	

Spring platform - Finding

Asset	Spring platform
Finding Title	Delamination of Wood
Finding Group	Maintenance
Cause	
Finding Status	Open
Finding Creation Date	28/10/2024 08:19:37
Resolve By Date	
Finding Resolved Date	
Risk Level	Low
Finding Notes	

Finding Photos



Previously Reported Findings (unresolved at time of Inspection)

- Clatter Bridge - Findings


Asset	- Clatter Bridge
Finding Title	Item - Timber rotting
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	Open
Finding Creation Date	30/05/2023 08:35:41
Resolve By Date	
Finding Resolved Date	
Risk Level	Medium
Finding Notes	Posts rotting

Finding Photos



Asset	- Clatter Bridge
Finding Title	Item - Timber rotting
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	Open
Finding Creation Date	30/01/2023 12:07:28
Resolve By Date	
Finding Resolved Date	
Risk Level	Low
Finding Notes	Will monitor post for rotting

Finding Photos



- Surface - Finding

Asset	- Surface
Finding Title	Surface - Edges Shrunk
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	Open
Finding Creation Date	29/06/2023 10:44:00
Resolve By Date	
Finding Resolved Date	
Risk Level	Medium
Finding Notes	Wet pour surface by swings - edges have shrunk. Potential trip hazard

Finding Photos



- Towers and platforms - Findings

Asset	- Towers and platforms
Finding Title	Delamination of Wood
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	Open
Finding Creation Date	29/07/2024 12:58:51
Resolve By Date	
Finding Resolved Date	
Risk Level	Medium
Finding Notes	Wooden posts are rotting - needs looking at

Finding Photos



Asset	- Towers and platforms
Finding Title	Item - Timber rotting
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	Open
Finding Creation Date	27/09/2023 11:19:57
Resolve By Date	
Finding Resolved Date	
Risk Level	Low
Finding Notes	Will monitor post

Finding Photos



2 bay swing Unit - Findings

Asset	2 bay swing Unit
Finding Title	Item - Cracked
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	Open
Finding Creation Date	30/08/2023 13:31:01
Resolve By Date	
Finding Resolved Date	
Risk Level	Medium
Finding Notes	Rubber broken on bar of swing - tape has been wrapped around- but needs repairing. Rubber on bar on the side of swing is also cracked.

Finding Photos



Asset	2 bay swing Unit
Finding Title	Item - Broken
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	Open
Finding Creation Date	30/01/2023 12:21:26
Resolve By Date	
Finding Resolved Date	
Risk Level	Low
Finding Notes	Rubber broken around bolt on seat

Finding Photos



Easy Access Roundabout - Finding

Asset	Easy Access Roundabout
Finding Title	Carousel - Bearings - Worn
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	Open
Finding Creation Date	30/05/2023 08:43:44
Resolve By Date	
Finding Resolved Date	
Risk Level	Medium
Finding Notes	Not turning properly and making a crating noise

Finding Photos



Rota web climber - Surface - Finding

Asset	Rota web climber - Surface
Finding Title	Surface - Trip points
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	Open
Finding Creation Date	29/06/2023 10:58:20
Resolve By Date	
Finding Resolved Date	
Risk Level	Medium
Finding Notes	Wet pour surface is lifting slightly as the wooden edges are rotten

Finding Photos



Wood Palisade fencing - Findings

Asset	Wood Palisade fencing
Finding Title	Item - Broken
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	Open
Finding Creation Date	29/07/2024 13:03:53
Resolve By Date	
Finding Resolved Date	
Risk Level	Medium
Finding Notes	2 wooden slats are broken and need replacing. Have put on hazard tape

Finding Photos



Asset	Wood Palisade fencing
Finding Title	Fencing - Panel damaged
Finding Group	Maintenance
Cause	
Finding Status	Open
Finding Creation Date	26/06/2024 12:09:38
Resolve By Date	
Finding Resolved Date	
Risk Level	Medium
Finding Notes	Fence slat broken at top - sharp edge have put hazard tape over

Finding Photos



Wooden fence gate - Finding

Asset	Wooden fence gate
Finding Title	Item - Repair/s - Minor
Finding Group	Maintenance
Cause	Wear and Tear
Finding Status	Open
Finding Creation Date	31/01/2022 11:06:35
Resolve By Date	
Finding Resolved Date	
Risk Level	Low
Finding Notes	Gate gas dropped slightly. Not easy to lock

Finding Photos

